

MADE IN
GT. BRITAIN

Ipeco

A Division of Ipeco Holdings Ltd

SEAT PILOT

SOUTHEND AIRPORT
ESSEX - ENGLAND

CUSTOMER PART NO S232T311-103

IPECO PART NO	ISSUE	SERIAL NO	INSPECTION
3A258-0041-01-1Z	1Z	79432	IPECO OP97
MODIFICATION	DATE		
SB258-25-14 ISS.5 SB258-25-08 ISS.6	10-3-22 10-3-22		

TSO NO

C127a

DATE MFG.

06-07-15

MODEL NO

0A258-0043
TYPE A-FF

TSO C127a TYPE A APPROVAL CONDITIONS

THIS SEAT DEVIATES FROM TSO C127a PARAGRAPH 3 IN
THAT THE FLOOR WARPAGE REQUIREMENTS OF SAE AS8049A
PARAGRAPH 5.3.1.3 HAVE NOT BEEN DEMONSTRATED. FOR
INSTALLATION LIMITATIONS SEE IPECO DOCUMENT No L006.

SEATING SYSTEM PART NUMBERS

SEATING SYSTEM	RESTRAINT	PAN CUSHION	BACK CUSHION
3A258-0041-01-1	5000-1-01A-()	0A254-0209	0A254-0511
3A258-0042-01-1	5000-1-02A-()	0A254-0209	0A254-0511



B 777 B 737
B 747 B 787







WARNING
REMOVING THE
SEAT CUSHION STRIPS
REMOVING THE SEAT

B 777
B 747
B 787





PUSH FORWARD - TO ADJUST

SEAT MUST BE IN
FORWARD 7 INCHES OF TRAVEL
DURING TAKEOFF AND LANDING

LIFEVESTS

ULINE
DIRECT THERMAL LABELS

100%
tre

DETAPE



B 777
B 747



B 781



