

PMA Data Sheet

7120M99P01-PMA CONNECTOR ASSEMBLY

OEM Part Number

7120M99P01, 7120M99P03

PMA Part Number

7120M99P01-PMA

Part Description

Connector Replacement and Upgrade Kit

Next Higher Assembly

7120M99P01, 7120M99P03

Assembly Description

Vibration Transducer

Installation

CF6

FAA Design Approval Means

Test & Computation per 14
CFR § 21.303

Quantity per Assembly

1

ATA Chapter

77

OEM

Meggitt

Product Improvement

Enables repair of the vibration transducer's weakest link, the connector assembly. The only OEM option is to scrap the unit.

Repair allows for connector replacement as often as necessary, which minimizes the purchase of new OEM assemblies.

